1961 Old Middlefield Way Mountain View, CA. 94061

JOB:

THEUERKAUF ELEMENTARY SCHOOL

DATE:

Apr. 10, 2018

## **INCREMENT #1 ONLY**

#### TIME:

SPEC SEC	ITEM	BASE AMOUNT	
	General Conditions	362,978	General Conditions
	Temporary Fence (nte 1500lf)	7,125	NTE 1500LF
1	Survey	N/A	None anticipated for this increment #1
	UG Locator	5,000	Allowance instructed for use in underground locating service
	Testing & Inspection	NIC / By District	
none	Abatement	15,000	Allowance instructed for use Testing, Removal or Handling of
			hazardous material of any kind has been excluded. No Reports
			have been made available at this time.
02 41 30	Demolition - Soft	197,067	Interior Walls, Acoustical Ceilings (Bldg. A & C), Carpet,
			Cabinet Bases - No ceiling removal in D,E,F & H
02 41 10	Concrete Demolition - Sawcutting Bldg. A & Bldg D,	12,900	Concrete removal work at Building A and interior toilet Bldg. D
	plumbing waste	Supreme of the Control of	and plumbing trench at relocated and new sinks. (incls.
31 10 /32	Site Concrete and Asphalt Walks, Curbs & Domes	139,536	Sawcutting, breakout & removal of site concrete and asphalt.
12 16/32 13			Aggregate base, reinforcing steel, concrete and asphalt at new
13	CO VINCOR ZOO IN	and the management	site walks and ramps. Remove concrete entry school sign.
3200	Building Concrete	15,850	Concrete replacement work at Building A & D, includes interior
renav stantas		I S FACE	plumbing trench
32 17 23	Striping/Signage	9,500	Striping & HC designation logo at asphalt paving and ramp, no
			new signage (none shown).
2811	Landscape Irrigation Repair w/wires	to the first of the second	Minor repairs at rerouting, no work on irrigation mains
none	Landscape Planting Repair		Minor patch (re-seed) at new walk at rear of Building D
none	Chain Link Fence & Metal Gates (4) Locations	40,000	Revised to include perforated metal, backing plates, panic
			device, and chain link gate revisions. Note - Panic device
			operation is highly questionable, may not work as designed.
055400	Character 1 & Miles - Matel Fels & Deals at Bide A Conons	24.400	Pending final design.
055120	Structural & Misc. Metal Fab. & Deck at Bldg. A Canopy		Columns, beam and deck at Bldg. A canopy
055120/05	Misc Fab - DS, DF rails & weld studs to column at Bldg.	14,160	Weld studs to column Bldg. A, 1 new DS, 2 sets DF railings .

1961 Old Middlefield Way Mountain View, CA. 94061

JOB:

THEUERKAUF ELEMENTARY SCHOOL

DATE:

Apr. 10, 2018

# **INCREMENT #1 ONLY**

SPEC SEC	ITEM	BASE AMOUNT	
06 10 00/ 06 20 00	Carpentry	255,054	Bldg. A (incls. rev. #1) walls, ceilings, soffits, backing, blocking. All rooms - AV wall ledgers and trim finish, fixture & backing at ceilings and walls. Dividing wall, soffit framing and new toilet rooms at Bldg. D. Exhaust fans at restrooms. Misc. cabinet and accessory blocking & backing.
06 41 16/12 36 23	3	252,860	New cabinetry, tops and reception desk at Building A (no locks). Cabinetry in Hall A15 not included per Rev. #1. New base cabinetry with tops at 22 classrooms (no locks). New doors and drawers at <e> cabinetry in classrooms and at H04,H06 &amp; H09 - reusing existing hardware. Cabinet relocation at Building G</e>
07 21 30	Insulation	16,110	Building A walls, minor repair to roof insulation at conduit installation at Bldg. C only. Existing insulation is intended to remain. No insulation at AV or exterior walls.
none	Built-Up Roofing	NIC	None shown or anticipated.
none	Metal Roof at Building A Canopy	A CONTRACTOR OF THE PARTY OF TH	Metal Roof at Canopy. No roof work for exhaust fan installation, none anticipated, none shown.
07 60 00	Sheet Metal Flashing & Trim	NIC-None Shown	
07 92 00	Caulk & Sealant		Plaster joints and various at entry.
08 11 13/08 14 16/08 71 00	Hollow Metal Frames, Doors & Hardware	110,848	All scope based on plans (not specifications - no hardware groups) No keying or Primus cylinders have been included.  Removable cores included.
08 31 00	Hardware Allowance Access Doors		Allowance instructed for approximately 30 additional locations. Cut-in type, 18"x18", non-rated, primed with flange and slotted screw latch.
08 51 13/08	Aluminum Windows & Storefronts	27,250	Building A only. Storefront and glazing of type C & D windows.
08 51 13	Aluminum Windows	NOT USED	Alternate for new windows deleted.

1961 Old Middlefield Way Mountain View, CA. 94061

JOB:

THEUERKAUF ELEMENTARY SCHOOL

DATE:

Apr. 10, 2018

#### TIME

TIME:			
SPEC SEC	ITEM	BASE AMOUNT	
05 40 00/09 29 00	Drywall & Metal Framing	248,419	Drywall at Building A (incls. Rev #1) and D over wood framing.  New metal stud and gyp board AV walls constructed using details previously approved for Crittenden MS. Patch & tape finish at ceiling fixture scars. No walls in Bldg. F
09 22 23 09 30 13 09 51 13	Lath & Plaster, Plaster Patching Ceramic Tile Rms. D17 & D18, patch at C08 & C10 Acoustical Panel Ceilings	6,600	Patching at Buliding A entry area only.  All tile set using thin set method - walls only.  Armstrong Prelude XL 15/16" 2'x2' and 2'x4' grid system with  Tectum lay-in tile at Building A. New Armstrong #741  12"x12"x1/2" (White) Staple-up mounting in Building C only.
09 65 00/09 68 00	Resilient & Carpet Floor Coverings	181,218	Minor patching in Bldgs. D, E, G & H. No work ing Bldg. F. Carpet - Mohawk Group Faculty Remix Illiminating Aqua #552 26oz. direct glue down. Armstrong Migrations T3510 12"x12"x1/8" direct to subfloor incls. 5% accent.
	Moisture Testing at floors Moisture Barrier		Moisture testing - by probe  Moisture Barrier if required at locations to be determined per test results.
09 67 01	Fluid Applied Epoxy Flooring	24,454	Tera-Gem III W&F/Poly 5100 TC - one pigmented seal coat of Tera-Gem III W&F and one pigmented seal coat of Poly 5100 following <e> contours at Rooms A09, A10, A13, C08, C10, D06, D12, D13, D14, H01, H02 and H03. AquaFin SG3/Tera-Gem III IFS/Poly 5100TC - at new rooms D17 &amp; D18.</e>
09 91 00	Painting	348,308	Exterior painting of all buildings, doors and window frames. Single body color. (Excluding Building B). Exterior paint - incls. fascia - not gutter - see roof coating. No painting of roofs. Paint Interior walls typically above 8' ht, incls. Soffits and doors. Includes painting of toilet rooms. No mechanical/electrical/storage rooms.
09 91 00	Painting - Graphic at Exterior Wall	8,628	Paint second color line at exterior walls where divided by metal channel only. (Add \$16,022 for graphic color line elsewhere.  Not used per architect)

**INCREMENT #1 ONLY** 

1961 Old Middlefield Way Mountain View, CA. 94061

JOB:

THEUERKAUF ELEMENTARY SCHOOL

DATE:

Apr. 10, 2018

## **INCREMENT #1 ONLY**

#### TIME:

BASE AMOUNT  Painting - Ornamental Fencing 09 91 00 Painting - Patch Holes and Paint  High Performance Metal Roof Coatings  Path Performance Metal Roof Coatings  Fabric Covered Tack Panels Markerboards  Not Included Markerboards  Not Included Markerboards  Not Included  Signage  11,980 Paint ornamental fence. Approx. 12 locations Patch holes and paint from door frame to door frame, beld electrical panduit where counter is removed. Coating at metal roofs - Projected cost is reasonably firm allowance amount - pending coverage determined by colo selection & mfg. recommendation. Amount is based on sin projects elsewhere in district. Includes front & bottom of autters. Tack panel work not used. Full ht. procelain steel markerboards with spline joints an clear satin aluminum trim. (22 AV wall locations only)  Signage  24,233 Signs made of 1/8" Rowmark Exterior materials, 5 yr. warr 10 44 00 Fire Extinguisher Installation  Hook mounted - no cabinets.	I IIVIL.			
Painting - Patch Holes and Paint  Painting - Patch Holes and Paint  Patch Holes and Paint  Patch holes and paint from door frame to door frame, beld electrical panduit where counter is removed.  Sou,000  High Performance Metal Roof Coatings  Sou,000  Painting - Patch Holes and paint from door frame to door frame, beld electrical panduit where counter is removed.  Coating at metal roofs - Projected cost is reasonably firm allowance amount - pending coverage determined by cold selection & mfg. recommendation. Amount is based on sign projects elsewhere in district. Includes front & bottom of autters.  Not Included  Patch holes and paint from door frame to door frame, beld electrical panduit where counter is removed.  Coating at metal roofs - Projected cost is reasonably firm allowance amount - pending coverage determined by cold selection & mfg. recommendation. Amount is based on sign projects elsewhere in district. Includes front & bottom of autters.  Patch holes and paint from door frame to door frame, beld electrical panduit where counter is removed.  Coating at metal roofs - Projected cost is reasonably firm allowance amount - pending coverage determined by cold selection & mfg. recommendation. Amount is based on sign projects elsewhere in district. Includes front & bottom of autters.  Patch holes and paint from door frame to delectrical panduit where counter is removed.  Coating at metal roofs - Projected cost is reasonably firm allowance amount - projects elsewhere in district. Includes front & bottom of autters.  Patch holes and panduit where counter is removed.  Coating at metal roofs - Projected cost is reasonably firm allowance amount - projects elsewhere in district. Includes front & bottom of autters.  Patch holes and panduit where counter is removed.  Southern to auters.  Signs and patch from to door frame to delectrical panduit where counters.	155	ITEM		
Painting - Patch Holes and Paint  Patch Holes and Paint  Patch Holes and Paint  Patch Holes and paint from door frame to door frame, beld electrical panduit where counter is removed.  Sou,000  High Performance Metal Roof Coatings  Sou,000  Painting - Patch Holes and Paint  High Performance Metal Roof Coatings  Sou,000  Patch holes and paint from door frame to door frame, beld electrical panduit where counter is removed.  Coating at metal roofs - Projected cost is reasonably firm allowance amount - pending coverage determined by cold selection & mfg. recommendation. Amount is based on sign projects elsewhere in district. Includes front & bottom of autters.  Not Included  Patch holes and paint from door frame to door frame, beld electrical panduit where counter is removed.  Coating at metal roofs - Projected cost is reasonably firm allowance amount - pending coverage determined by cold selection & mfg. recommendation. Amount is based on sign projects elsewhere in district. Includes front & bottom of autters.  Not Included  90,288  Full ht. procelain steel markerboards with spline joints an clear satin aluminum trim. (22 AV wall locations only)  Signs made of 1/8" Rowmark Exterior materials, 5 yr. warr for the performance of the projects elsewhere in district. Includes front & bottom of autters.  Signs made of 1/8" Rowmark Exterior materials, 5 yr. warr for the performance of the	09 91 00	Painting - Organization Fencing	11 080	Paint ornamental fence Approx 12 locations
High Performance Metal Roof Coatings    Souther Street Covered Tack Panels   High Performance Metal Roof Coatings			7	
High Performance Metal Roof Coatings  500,000  Coating at metal roofs - Projected cost is reasonably firm allowance amount - pending coverage determined by color selection & mfg. recommendation. Amount is based on sing projects elsewhere in district. Includes front & bottom of autters.  Not Included  Fabric Covered Tack Panels  Markerboards  Not Included  Full ht. procelain steel markerboards with spline joints and clear satin aluminum trim. (22 AV wall locations only)  Signage  24,233 Toilet Accessories  Fire Extinguisher Installation  Hook mounted - no cabinets.	09 91 00	Familing - Faton Holes and Famil	14,720	
allowance amount - pending coverage determined by color selection & mfg. recommendation. Amount is based on sin projects elsewhere in district. Includes front & bottom of outters.  Tack panel work not used.  Markerboards  Not Included  90,288  Full ht. procelain steel markerboards with spline joints an clear satin aluminum trim. (22 AV wall locations only)  Signage  10 14 00  Signage  Toilet Accessories  Toilet Accessories  Fire Extinguisher Installation  Amount - pending coverage determined by color selection & mfg. recommendation. Amount is based on sin projects elsewhere in district. Includes front & bottom of outters.  Tack panel work not used.  Full ht. procelain steel markerboards with spline joints an clear satin aluminum trim. (22 AV wall locations only)  Signs made of 1/8" Rowmark Exterior materials, 5 yr. warr 8,570  Hook mounted - no cabinets.	00.00.00	High Defendence Matel Deef Continue	F00 000	
selection & mfg. recommendation. Amount is based on single projects elsewhere in district. Includes front & bottom of autters.  Tack panel work not used.  Markerboards  Not Included  90,288  Full ht. procelain steel markerboards with spline joints an clear satin aluminum trim. (22 AV wall locations only)  Signage  70 ilet Accessories  Toilet Accessories  Fire Extinguisher Installation  Selection & mfg. recommendation. Amount is based on sing projects elsewhere in district. Includes front & bottom of autters.  Tack panel work not used.  Full ht. procelain steel markerboards with spline joints an clear satin aluminum trim. (22 AV wall locations only)  Signage  70 ilet Accessories  8,570  Hook mounted - no cabinets.	09 99 00	High Performance Wetai Roof Coatings	500,000	
projects elsewhere in district. Includes front & bottom of outters. Tack panel work not used.  Markerboards  Signage  Toilet Accessories  Fire Extinguisher Installation  Not Included  Not Included  Not Included  Not Included  Not Included  Projects elsewhere in district. Includes front & bottom of outters. Tack panel work not used.  Full ht. procelain steel markerboards with spline joints an clear satin aluminum trim. (22 AV wall locations only)  Signs made of 1/8" Rowmark Exterior materials, 5 yr. warr  8,570  Hook mounted - no cabinets.				
Tack panel work not used.  Not Included  90,288  Fabric Covered Tack Panels Markerboards  10 11 22 none Markerboards  10 14 00 Signage Toilet Accessories Fire Extinguisher Installation  Not Included  90,288 Full ht. procelain steel markerboards with spline joints an clear satin aluminum trim. (22 AV wall locations only) Signs made of 1/8" Rowmark Exterior materials, 5 yr. warr 8,570 6,765 Hook mounted - no cabinets.	1			
10 11 22 Fabric Covered Tack Panels none Markerboards  Markerboards  Signage  Toilet Accessories  Tack panel work not used.  90,288  Full ht. procelain steel markerboards with spline joints an clear satin aluminum trim. (22 AV wall locations only)  Signs made of 1/8" Rowmark Exterior materials, 5 yr. warr  8,570  Toilet Accessories  Fire Extinguisher Installation  Not Included  90,288  Signs made of 1/8" Rowmark Exterior materials, 5 yr. warr  8,570  Hook mounted - no cabinets.	1			• No. 4 September 1998 - Control of the Control of Cont
none Markerboards 90,288 Full ht. procelain steel markerboards with spline joints an clear satin aluminum trim. (22 AV wall locations only)  10 14 00 Signage 24,233 Signs made of 1/8" Rowmark Exterior materials, 5 yr. warr 7 10 28 00 Toilet Accessories 8,570 Fire Extinguisher Installation 6,765 Hook mounted - no cabinets.	10 11 22	Eabric Covered Tack Panels	Not Included	
clear satin aluminum trim. (22 AV wall locations only)  10 14 00 Signage Toilet Accessories 10 24 00 Toilet Accessories Fire Extinguisher Installation  clear satin aluminum trim. (22 AV wall locations only) Signs made of 1/8" Rowmark Exterior materials, 5 yr. warr 8,570 Hook mounted - no cabinets.	100000000000000000000000000000000000000			
10 14 00 Signage 24,233 Signs made of 1/8" Rowmark Exterior materials, 5 yr. warr 10 28 00 Toilet Accessories 8,570 Fire Extinguisher Installation 6,765 Hook mounted - no cabinets.	none	Ivialkerboards	90,200	
10 28 00 Toilet Accessories 8,570 10 44 00 Fire Extinguisher Installation 6,765 Hook mounted - no cabinets.	10.44.00		04.000	
10 44 00 Fire Extinguisher Installation 6,765 Hook mounted - no cabinets.		9 9		
		A T 11 T 1 T 1 T T T T T T T T T T T T T		Part 2 as to transfer to
		1		Hook mounted - no cabinets.
	none	Projection Screens	None Shown	
12 49 20   Window Treatment - Mini-blinds   22,996   1" mini-blinds at exterior windows. No blinds at restroom	12 49 20	Window Treatment - Mini-blinds	22,996	[14]
	1	l Y		windows, any blinds at arched and divided windows will be
straight and surface mounted per elevations. No shades				
	1			included. No coverings at door lites. Verticals in Bldg. H -
protect in place (carefully however likely brittle & easily su				protect in place (carefully however likely brittle & easily subject
to damage				to damage
none Fire Sprinkler System NIC/None Shown	none	Fire Sprinkler System	NIC/None Shown	
22 00 00 Plumbing Included Below	22 00 00	Plumbing	Included Below	

1961 Old Middlefield Way Mountain View, CA. 94061

JOB:

THEUERKAUF ELEMENTARY SCHOOL

DATE:

Apr. 10, 2018

# **INCREMENT #1 ONLY**

TIME:

I IIVIC.			
SPEC SEC	ITEM	BASE AMOUNT	
22 00 00/23 00 00	Plumbing and Mechanical Systems	279,690	PLUMBING - Underground piping (at Bldg. D) shown on clarification dwgs. P2.0 & C2.3 (POC locations have not been field verified for existance or accessibilty). Piping and fixtures for Building D at new toilet rooms. New faucets and flush valves as revised for existing fixtures in toilet rooms - connected to existing - no new piping - no work in walls. One new DF w/bottle filler at Building C and one new DF without bottle filler at Bldg. G per A7.6. New sink at Building A as proposed sink will have 2" drain line stub out wall above foundation for exterior connection. HVAC - New ducting at Building A, exhaust fans at toilet rooms, registers. Controls - New thermostats where shown to be Johnson Controls No work in Building B or Building F
23 09 00 26 00 00	Control Systems - Electrical Systems	Included Above 2,135,963	Under Review - Clarification of Scope Power, lighting and lighting control system. Lighting fixtures revised to surface mount - fixture count by change to new fixtures is one to one. Location and orientation of fixtures to remain as is existing. New surface mtd. fixtures will be mounted to existing blocking and existing power locations - no ceiling removal, no new blocking. Other lighting devices to be surfaced mounted. Includes AV Frontrow system - district to provide TV monitors and mounts. Teledata cabling and outlets as shown. (IDF at Bldg. G). Re-use existing UG pathways - No underground conduits or excavations.
27 00 00 27 00 00	Technology Systems Security System - Building A Only	Included Above Included Above	See above. Security Devices not shown on floor plan. Security in Building A only per riser diagram.

1961 Old Middlefield Way Mountain View, CA. 94061

JOB:

THEUERKAUF ELEMENTARY SCHOOL

DATE:

Apr. 10, 2018

## **INCREMENT #1 ONLY**

TIME:				
SPEC SEC	ITEM		BASE AMOUNT	
27 51 23	Clock/Speaker/Intercom		*	Allowance instructed for clock/speaker/intercom system. No work shown on plans. No scope included in proposal. No removal or in-fill of existing or cut-in for new. No power or data. No Locations shown.
28 31 00	Fire Alarm Systems		Included above in Elect. Sys.	Fire Alarm System and devices. Re-use existing pathways. No underground conduits or excavations. Device locations in rooms subject to review. Surface mounted at hard lid ceilings and at revised ceiling locations, all buildings.
	TOTALS ABOVE		5,902,614	
	PERMITS & FEES SUBCONTRACTOR BOND PERMITS & FEES @ E & O INSURANCE		N/A Not Used Not Included Not Used	
	BUILDER'S RISK INSURANCE		11,600	
	LIABILITY INS. @	0.60%	Value of the same of	
	FEE @	3.745%		li de la companya de
	PERFORMANCE BOND	1.15%	Laborator Street Contraction	
	ALLOWANCE 10%		624,350	
	ADJUSTMENTS		0	
	TOTALS AMOUNT		6,875,029	